


SUITE 1060



**SUITES 1100, 1120,
1150 & 1160**



Suites 1100, 1120, 1150, and 1160 are all contiguous.

SUITE NO.	RSF	STATUS	DESCRIPTION
Suite 1100	6,745	Vacant	Double-door entry. Shell condition. Expansive south-facing views.
Suite 1120	4,492	Vacant	Spec Suite with excellent west facing views. 4 offices (or 3 offices & conference room), reception & print/copy area.
Suite 1150	2,010	Vacant	New Spec Suite. Double door entrance off elevator lobby, efficient office buildout, 5 window-line private offices, conference room, kitchenette, open area, reception
Suite 1160	4,915	Vacant	Shell condition & ready for custom tenant improvements.